
Transboundary Spill NPDES CA0108928 Order No. R9-2014-0009, Amended by R9-2014-0094						
Type _A_ B 0/ 3/17/8 (CAL OES 1-800-852-7550)						
Name of Person Reporting Spill Carlos Pena						
Telephone No. of Person Reporting619-210-1370						
Spill Location/Name Tijuana River at the International Boundary						
<b>GPS Coordinates</b> 32.32.30 N, 117.2.18 W						
Spill Reached:Drainage ChannelDrainage StructureXXXSurface Water						
Spill Reached:MS4						
Vol Spill to MS4Vol Recovered from MS4						
Estimate Spill Volume from All Sources Approx. 304,000 Gallons						
Volume That Reached: Surface Water, Drainage Channel, Not Recovered from MS4 Approx. 304,000						
Gallons						
Total Recovered Volume						
Number of Spill Appearance Points1						
Appearance Descriptions Slighty Clear Water						
Spill Flow: Start Date 02/20/18 Start Time Approximately 0900						
Notification: Date02/20/18 Time1300						
Operator Arrival: Date <u>02/20/18</u> Time <u>8000</u>						
Spill Flow: End Date <u>02/20/18</u> End Time <u>1100</u>						
Cleanup Completed: DateNA Time						
Probable Cause of Spill Partial intentional shutdown of Pump Station to replace elect. equipment						
Notification of CAL OES Date 02/21/18 Time 0930						
CAL OES Control Number 18-1164 Randall Perez						
Description of Spill Flow Destination Tijuana River Channel						
Spill Flow Cause Partial intentional shutdown of Pump Station to replace elect. equipment						
Spill Flow Failure Point Pump Station CILA						
Spill Flow Storm Event N/A						
Spill Corrective Actions None						
Spill Flow Response Actions None						
Spill Flow Completion Date 02/20/18						
InvestigationN/A Reasons Completion Date						
Health Warnings Posted YesX No						
Name of Beaches Impacted: None Surface Water Impacted: Tijuana River						
Location and No. Of Samples Collected (Type A) N/A Number						
Parameters Tested N/A						
Regulatory Agencies Receiving ResultsN/A						
Methodology for Spill Volume Estimate Flow Rates at UISBWC Metering Station						
Amount of Spill Recovered						
I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a						
system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the						
best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information,						
including the possibility of fine and imprisonment for knowing violations.						
Certifying Official Carlos Pena Title Area Operations Manager Date 02/23/18						
Signature CARLOS PENA Digitally signed by CARLOS PENA						



## US Section, IBWC

## Tijuana River Gage



Date	Disc	charge (m3/s)			
2/20/2018	8 8:45	0	0	0	1
2/20/2018	9:00	0	0	0	1
2/20/2018	9:15	0.097133	0	0	1
2/20/2018	9:30	0.194266	0	0	1
2/20/2018	9:45	0.24977	0	0	1
2/20/2018	10:00	0.24977	0	0	1
2/20/2018	10:15	0.24977	0	0	1
2/20/2018	10:30	0.194266	0	0	1
2/20/2018	10:45	0.041628	0	0	1
2/20/2018	11:00	0	0	0	1